Manhole Inspection Summary Manhole # S13CC 041MH Printed On: 8/20/2009 Page 1 of 3 Inspection ✓ Is Incomplete Rating: Record Plat: 13CC Node: **041** Status: Not Found Insp Date: 8/3/09 2:02 PM Incomplete Comments Crew: ADS4 Cannot Access - Buried - Manhole Existing Confirmed by Inspector: ADS1 **CCTV** Firm: ADS Location Address: 1110 N DUKELAND ST Cross Street: RIGGS AVE **Manhole** Type: Location: **Ground Conditions:** Weather: **Dry** Subject To Ponding: None Prev. Rehab Comments ATTEMPTED LOCATION ALONG ALLEY BETWEEN DOWNSTREAM NODE 025 UPSTREAM TO BEHIND HOUSES ON DUKELAND AVE WITH METAL DETECTOR. **RECEIVED NO POSITIVE RESULTS.** Cover Diameter: Shape: (in.) Length: (in.) Dist A/B Grade: (in.) Type: Sanitary Condition: Cover Material: Cast Iron Properties: Bolted Vented Condition: Sound **Frame** Offset: (in.) Cracked Leaks **Chimney / Frame Adjustment** Exists Material: Parged Height: (in.) Condition: Sound Cracked Root Intrusion ☐ Loose Brick ☐ Deteriorated Infiltration: None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall Corbel Material: Parged Type: Condition: Sound Cracked Root Intrusion ☐ Loose Brick ☐ Deteriorated Infiltration: None Joint Cracks Mortar Roots Wall Barrel Material: Parged Shape: Diameter: (in.) Length: (in.) Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated Infiltration: None Joint Cracks Mortar Roots Wall **Bench** Exists Material: Parged Condition: Sound Cracked Root Intrusion ☐ Deteriorated ☐ Leaks Debris Channel Material: Parged Junc Dist: 0 Channel Exposure: Fully Open nearest .5 ft. Azimuth:

☐ Deteriorated ☐ Leaks

(ft.) Active Surcharge Present

Debris

Condition: Sound Cracked Root Intrusion

Evidence Of Surcharge

Missing:

Corroded

Depth:

Count:

Steps

Surcharge

Manhole Inspection Summary

Manhole # S13CC_041MH

Printed On: 8/20/2009 Page 2 of 3



CAN NOT LOCATE MH @ ALLEY AS SHOWN ON MAP

Manhole Inspection Summary

Manhole # S13CC_041MH

Printed On: 8/20/2009 Page 3 of 3